G. R. S. 59]

GENERAL AND REVENUE SECRETARIAT.

1907
(Muzrai)

File No. 365

Serial Nos. 1-3

Papers Filed.

Month November 1907

SUBJECT.

Repairs to the Sri Yoga Nara-simhaswamy temple at Melkote

PREVIOUS REFERENCES	LATER REFERENCES
Muzy. 150 - 92	

150 - 93.

MUZRAI SECRETARIAT.

OFFICE NOTE.

File No.

SUBJECT.

Repairs to the Sri Yoganarasimha Swami temple at Melkote.

From

The Chief Engineer of Mysore

Letter No. 7704 Dated 4th November 1907

During the inspection of the Sri Yoganarasimha Swami temple at Melkote by the Muzrai Secretary on the 26th March 1907, he was shewn certain items of works ~~in the temple~~ requiring early attention. Thereupon the Chief Engineer was requested to depute one of the Officers of the P. W. Department to inspect the temple and submit separate Estimates for the works.

He forwards an Estimate for Rs 2083/- for repairing the Sri Yoganarasimha Swami temple at Melkote together with a report explaining the several items of works proposed to be carried out

The Estimate has been prepared by the Supervisor No 4 Sub Division and Mr P S Subba Rao, Executive Engineer says that the works estimated for are all necessary

20 lamp posts of iron rails with lanterns &c at a Cost of Rs 320/- have also been provided as requisitioned by this Office

The usual Establishment and tools and plant charges of 10 1/2 % have also been provided.

The temple accounts of June 1907 & of the year 1906-7 have not yet been received From the annual account of 1906-7 of the Seringapatam Taluk, it is observed that the following amounts are available at the credit of the Sri Narasimha Swami temple at Melkote:—

Rs 1422-10-4	In temple funds
1953-9-4	In Savings Bank
1085-7-0	In Pro Notes
Total Rs 4461-10-8	

Muzrai Secretariat. | File No. of 190

Submitted with a draft requesting the Compt. to Govt.; to furnish infn. regarding the exact amount available at the credit of the Temple.

W 18/10/07

I find on examination of the Estimate that the cost of erecting a compound wall round the pond is very large being Rs. 1273. The work need not be undertaken now. The cost of fixing lamp posts and lanterns is Rs 372. The cost of maintaining these lamps and the establishment required therefor will be considerable. This work also need not be undertaken at present. Put up a draft sanctg. the remaining works which amount to Rs 440 & request that the D.P.W. may have it carried out carefully: the supervision

File No.   of 190 | Muzrai Secretariat.

×Charges are already included in the Estimate. Issue also the Draft [illegible]

16-11-07

off subd 16 11 07

Issue
19/11/07

Subpd
a separate
office note is
subpd by
W. Vollmer

[illegible]

~~and~~ write
~~[illegible]~~ [illegible] ask
this

[illegible] 19
16

[illegible]

[illegible] 19

[illegible]

[illegible]

[illegible]

[illegible]

[illegible] 1906-07 [illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible] 51948-8 333-9-1 296
8497-1-3

[illegible] ~~[illegible]~~ 1953-9-4 10
[illegible] -1422-10-4

4461-10-8

[illegible] [illegible]
[illegible]

12.11.0[illegible]

Let this be explained to me
14.11.[illegible]

I will explain this

26/7

Draft on Inspection Notes.

Muzrai

No. 47/dt/07.7.07

J. Ch.

To

The ~~Deputy Commissioner~~ Chief Engineer of Mysore,

~~Mysore District~~

Sir,

During my inspection of the Sri Yoga Narasimhaswami temple at Melkote on the 26th March ult, the following items of works were shown to me as requiring early attention:-

(1) A portion of the compound wall, which is tacked on to the Gopuram has given way, thereby causing a large crack. This has to be repaired

(2) There is a crack in the stone slab on the top of the stone frame in the inner entrance leading to the steps. This has also to be repaired.

(3) A parapet wall is required to be put up around the ~~tank~~ small pond on the hill

x (4) Lamp posts have to be fixed on the steps from the bottom to the top of the hill ~~as~~ for the convenience of ~~the~~

pilgrims during dark nights.

2. I am directed to request that you will be so good as to depute one of your officers of the P.W. Dept to inspect the temple and submit separate estimates for the above works.

3. The favor of a reply is requested.

I have &c,

13/7/09

Secretary

Copy to the Deputy Commissioner Mysore Dt., for infn.

By order,

Secretary.

9½

Please regd. & put up papers
7/11/07
bv

ana

MYSORE GOVERNMENT
1976
7/11/07
MUZRAI SECRETARIAT

Note Subd.
8/11/07
Off. subd. 16/11/07

1907.

FROM

THE CHIEF ENGINEER OF MYSORE,
BANGALORE.

To

The Secretary to Govt. of
H. H. the Maharaja of Mysore
Muzrai Department
&c. &c.

Dated 4-11-07
Despatched
Received
General No. 7704
No.

Enclosure No. 2.

Sir,

In compliance with your letter No. 471/I.N of the 27th July last, I have the honor to forward herewith an estimate amounting to Rs 2083/- for repairing the Sri Yoga Narasimhaswami temple at Melkote.

E

2. The report explains the several items of work proposed to be carried out.

I have the honor to be,
Sir,
Your most obedient Servant,

Bernard Davis.
Captain R.E.
Deputy Chief Engineer
of Mysore.

by

GPB—10,000—12-12-06

20/11

Muzrai

Read:—

Letter No. 2 dated 4th November 1907, from the Chief Engr- of Mysore, forwarding an estimate amounting to Rs 2083/- for repairing the Sri Yoganarasimhaswami temple at Melkote.

o.2483-5 D/23.11.07.
Encs. 1 Abstract estimate
1 Estimate &
1 report
&
" 1 Copy of A. Estimate

Order thereon No-

During the inspection of the Sri Yoganarasimhaswami temple at Melkote by the Muzrai Secretary, he was shewn certain items of works requiring early attention. Thereupon, the Chief Engr. was requested to forward estimates for the necessary works required to the temple. With the letter read above, the Chief Engr. submits for sanction an estimate for Rs 2083/- for the repairs needed thereto together with a report explaining the several items of works to be carried out, providing therein the usual Establishment and tools and plant charges.

2. On examination of the estimate, it is observed that the of erecting a

compound wall round the pond is very large being Rs 1273. The cost of fixing lamp posts and lanterns is Rs 372/- The cost of maintaining these lamps and the establishment required therefor will be considerable. The Government therefore direct that the above mentioned two items of works need not be undertaken at present.

3. The Government are pleased to sanction the remaining items of works provided for in the estimate which amount to Rs 440/-

The Chief Engr. is requested
to have the sanctioned
works executed by
the D. P. W. The cost of the works sanctd. will
met from the funds of the matu & the Compt.
is requested
amount at
of the P.W.D.

Dft

19/11/07
Secretary.

W 19/11/07

To,

The Chief Engr.,
with the sanctioned Estd.
& report.

" " Comptr., with a
copy of the Abstract
Estd.

" " Dy: Comr., Mysore
Dt., for infn.